



November 2020 Public Release

2020-11-11 - EFILive Support - Comments (0) - Download

Release Notes:

EFILive V8

Enhancements:

PR

- Added Run Mode/Boot Mode/Unknown Mode status display for Cummins HD controllers on [F4: OBD].
- Reduced screen flicker when closing editor tab pages.
- Added *.cax8 editing support for E55, E69 and E77.
- Added editing support for E40.
- Added editing support for E20.
- Added editing support for E86A and E86B.

RC5

- When changing the PID selections for scan tool maps, all three options (Data, Column and Row) PID selection menus now appear in the right-click context menu regardless of where the right-click occurs. Previously you were required to click on the map title to select the data PID, or the col/row axis labels to select the col/row PIDs.
- Added VE table units selection in Edit -> Properties -> Tuning Tool -> Settings. Changes are displayed in real-time, no need to close/re-open the tune file when changing units.
WARNING: Undo/redo information is discarded for all open VE tables if/when the VE display units are changed, which means changes to VE tables cannot be undone/redone after changing the VE display units.

RC4

- The [Check firmware] option for V3 devices now advises the user that "Some firmware updates also contain a boot block update. After a firmware update, please check the device's screen for a possible boot block update".
- In the tune editor, the mouse scroll wheel now scrolls the data table if the data table does not fit vertically on the screen. Previously the mouse scroll wheel only controlled the 3D zoom level. Now, to control the 3D zoom level using the mouse wheel, hold the Ctrl key down while scrolling the mouse wheel.

- Added three new script functions for manipulating calibrations:
(see EFILive Command Line Reference.pdf for more info)
 1. `efiGetCalInterp()` which retrieves interpolated values from a calibration.
 2. `efiGetColPos()` which retrieves the column position for use with the `_efiGetCalInterp()` function.
 3. `efiGetrowPos()` which retrieves the row position for use with the `_efiGetCalInterp()` function.
- Updated the `_efiGetCalValue()` function to allow row and column text labels for calibrations that use text labels in their axis.
- New warning is now visible when alternate calibration data is being interpolated due to axis differences between the main and alternate calibrations.
- New Copy/Paste option to optionally allow copying/pasting of calibration enumerated text values instead of just the underlying numerical data.

RC3

- None.

RC2

- Copy to clipboard is now supported for copying selected text from the calibration descriptions.
- Merged the DTC codes and DTC MIL tables into a single composite table for LS1, E54/E60, E37/E38/E67 controllers.
- When creating *.cax8 files, you may now reference EFILive provided axis calibrations without re-defining them in your *.cax8 file. EFILive will first search for the axis calibration in the *.cax8 file's Unique ID name-space, if not found, it will then search in EFILive's default name-space.
- When running updates from the [Compare] tab page, any mis-defined calibration that results in calibration values of NAN (Not A Number) will not be updated from the ALT to the CAL calibration.
- Warnings are now displayed if/when calibrations cannot be updated due to NAN or range errors. A text report of all failed and interpolated updates is now displayed at the end of the update process.
- LBZ/LMM (E35A/E35B) DTCs are now displayed correctly.

RC1

- Changed the tune tool editor's right-click paste menu hierarchy to be identical to the V7 menu hierarchy.
- Changed the way PIDs are inserted when clicking on the PIDs in the right hand panel of the calculated PIDs editor. If a PID name (or the literal text "PID") is currently highlighted, then the highlighted text is replaced with the selected PID. If not, then the entire `pid()` function is inserted, e.g. `pid("ECM.RPM")`. The scan/tune linking now automatically converts between PID units and tune table axis units that are both

metric but not identical, (for example kPa and MPa) .

- The scan/tune linking now automatically converts between PID units and tune table axis units that are both metric but not identical, (for example kPa and MPa) .
- Updated firmware re-programming routines to handle transitions into and out of dead-poll mode more seamlessly.
- Script conversion from V7 to V8 now generates scripts with more robust error reporting.
- The Ctrl+Alt+X "Reload cax8 files" option, now reports how many and which *.cax8 files were reloaded.
- Added [F3: Tune] -> [F9: Scripting] -> [Create] option to create a script file based on the differences between two tune files.
- Added right-click context menu to script editor windows that includes Find and Find/Replace options, along with the usual cut/copy/paste options.

Beta 52

- Added a warning that displays before V7 script files are converted to their V8 Lua script equivalents. the warning explains that the user is responsible for converting non-metric units used in the V7 scripts to their metric equivalent in the V8 Lua script.
- Converted the V7 script files for initializing DSP2 and DSP5 custom operating system data to their V8 Lua script equivalents.
- The [F3: Tune] -> [F5: Edit] -> [Convert] -> [Create New Table] button now supports creating tables from clipboard data that has no label information. Labels are generated automatically from 1..n to fit the data being pasted.
- Two new clipboard formats for table data are now supported:
 1. V7 script file data tables.
 2. V8 Lua script file data tables.You may now copy and paste those data tables from their scripts into any calibration table.
- The copy to clipboard option now has a new option to "Copy as Lua Source" which will copy the selected data, formatted as a table in Lua source code. That table can be pasted directly into EFILive Lua scripts.

Beta 51

- The warning message displayed prior to running a script from the [F3: tune] -> [F9: Scripting] tab page may now be hidden if required.
- When loading multiple *.cax8 files, the software no longer stops loading additional files after the first error. Now, all *.cax8 files are attempted to be loaded. If errors are detected, a list of filenames, line numbers and error messages will be displayed to the user.
- When comparing two tune files, if all edit tab pages were closed then the tool bar button to display the [Compare] tab page was incorrectly being disabled.

- Added Properties -> Tuning Editor -> Editor -> "Allow Cax8 in OS Memory" option to allow cax8 calibrations to be defined in the operating system memory for the following controllers only: LS1A, LS1B, P10, P12, L31, P08, P11, T42, T43, T76, T87, AL5, A40 and A50.

Beta 50

- Added "UniqueID" option when using cax->cax8 conversions to allow a unique ID to be added to the converted cax8 file. That unique ID is used to prefix calibration and axis names to help mitigate naming conflicts between third party calibration providers.
- Updated the calibration search option to allow searching of calibration names without needing to specify the prefix. Place the @ symbol before any single search word to search only for calibrations with that name. For example, to search for calibrations named SparkHigh, use @SparkHigh, that will find all calibrations with the name SparkHigh, regardless of any unique ID prefix.

Beta 49

- Updated E41 DMA PIDs.
- For each calibration provider details are now shown in a new tab page called [Provider]. That allows users to determine if a calibration is provided by EFILive or is provided via a third party *.cax8 file.
- Multiple *.cax8 files can now be loaded for each controller's operating system. Just name the additional *.cax8 files with the OS number followed by an underscore then a unique suffix, like this: 12345678_suffix1.cax8, 12345678_suffix2.cax8, 12345678_suffix3.cax8, etc.

Beta 48-7

- Torque table validations are now included in the V8 tune editor.

Beta 48-6

- Updated PID selections for AL5 controller.
- [F4: OBD]-[DTC] now displays permanent DTCs alongside the usual current and pending DTCs.
- Added screen capture options to the tune tool editor.
- [F5: BBX]->[Quick Setup] will now display any device settings from the current *.bbx file when editing device settings via the [Edit ... Settings] button and the drop down menu options.
- [F6: Device Settings] can now open *.bbx files to extract and display any device settings contained in the *.bbx file.
- Added additional information to *.cax -> *.cax8 conversion process to help pinpoint conversion issues in the original *.cax file.

Beta 48 (4)

- When an AutoCal configured to self-sign reads either an E54 (LB7) or an E60 (LLY) controller, the tune file is now self-signed with the correct serial numbers.
- The "Clear DTCs" procedure at the end of the read/flash operation has been updated.
- Save/Save As are now enabled by default in the [F6: Devices] tab page after reading the device settings from a FlashScan or AutoCal device.
- Cummins HD pass-thru data logging would log corrupt data if invalid PIDs were selected.
- Cummins HD pass-thru data logging would always fail to start with "no controllers detected" error.

Beta 48 (3)

- Replaced USBView.exe utility with the more comprehensive USBTreeView.exe in the Drivers\Utilities folder.

Beta 48

- TCM licensing is now free for both V2 and V3 devices.
- FlashScan/AutoCal V3 VIN license slot count has been increased from 221 to 600.
- Scan, tune and other windows can now be managed more easily via the Windows Task Bar - or via new drop down button menus in the lower left corner, or via hotkeys.
- Software registration is not required.
- Manage customer details per vehicle and use customer details in scan and tune file name templates.
- User defined calibrations conversion process from V7 *.cax file format to V8 *.cax8 format.
- User defined script conversion process from V7 *.txt format to V8 *.Lua format.
- V3 devices can be configured to appear as a USB thumb drive in Windows Explorer, allowing file transfers and management to be performed without installing the EFILive software.
- Tune file editor is available for selected controllers and operating systems:
- Tune file comparison between different operating systems.
- Scan and tune file linking is now supported.
- V3 devices support black box data logging without upgrading to CSP5.
- Dodge Cummins FAST CAN mode can be configured as a device setting.
- Custom, user defined menu systems can be created for V3 devices.
- The EFILive EULA is displayed and must be accepted each time a V3 device is powered on before it can be used in standalone mode.
- AutoCal's linked/unlinked status is displayed at the bottom of the EULA screen.
- Transferring files to/from V3 devices is up to 10 times faster than V2 devices.
- And many more...

Bug Fixes:

RC6

- Cummins HD CM2150 "Force All Checksums to be Correct" option was not working.
- Added additional checks at the end of a Cummins HD flash to ensure reflash completed successfully.
- When comparing two tune files, displaying VE table alternate values was not possible if the VE units had been changed from the default g*K/kPa units to % or g/cyl or g/sec.
- After closing the scan tool gauge property editor, attempting to resize the scan tool window causes an access violation.
- Font selection dialog box was incorrectly dragging the EFILive main window to the front when activated, obscuring the window containing the component(s) being edited.
- Fixed font size selection problem in the font selection dialog box.
- Added missing icons on OK/Cancel button in the font selection dialog box.

RC5

- Changes to the CMF flash script for more stable failed flash recovery.
- Fixed P12 (IL5/L52) calibration fault that caused incorrect values to be stored for some speedo calibrations for OS 12627884.
- Transferring files from FlashScan/AutoCal V2 devices to the PC using EFILive Explorer would fail with error code \$0106.
- Fixed E98 DMA PIDs that were not displaying correct data.
- Menu text for "Next Scan Window" and "Next Tune Window" was missing from the drop-down menu of the Scan/Tune buttons in the lower-left corner of the main window and sub-windows.
- A/D voltages were not being captured/displayed when pass-thru logging with FlashScan V2.

RC4

- When opening a log file from the main V8 window, the two [Scan] and [Tune] buttons in the lower left were being overwritten with text labels.
- Comparing Diagnostic Trouble Codes (DTCs) between different operating systems now works correctly.
- Displaying ALT Diagnostic Trouble Codes (DTCs) when comparing different operating systems now works correctly.

RC3

- None.

RC2

- If the most recently used Options.txt file cannot be loaded when opening the [F5: BBX] window the window would fail to open.
- If the most recently used Settings.dat file cannot be loaded when opening the [F6: Devices] window the window would fail to open.
- Hex values now display CAL and ALT values correctly depending on which calibration is currently selected for display.
- Hex values now display correctly in the [Compare] tab page.
- Removed absolute/relative options for script generation, scripts are now only generated using absolute values. Due to the potential for overlapping calibrations, scripts generated using the "relative" option would apply relative updates multiple times (as many times as a calibration is defined), causing unintended results.
- When auto-generating scripts, calibration identifier names were being incorrectly created with a dot in the name (between the Unique ID and the calibration name) if the calibration was defined in a *.cax8 file that included a Unique ID.
- Some list-based calibrations, such as DTCs and related OBDII enablers were not displaying nor updating the correct data in the tune file.
- Fixed a number of bugs and display issues when setting up axis labels for scan tool maps.
- User's default units preferences are now applied correctly when opening calibrations.

RC1

- Fixed row axis labels for E38/E67 calibration G0901 that were not updating after the B9904 fan patch was applied.
- Fixed failure caused by some USB configurations that fail to provide accurate USB location ID information to the USB driver.
- Read-Only calibrations are now strictly read-only in the V8 editor and cannot be changed.
- Changed the "Cax8 Reload" hotkey from Ctrl+Alt+O to Ctrl+Alt+X. The Ctrl+Alt+O hotkey was already in use to decrease the calibration display precision.
- The script function _efiGetRowAxis() was returning column labels instead of row labels.

Beta 52

- Some old V7 scripts used label 0 to reference a single column with the label "Value" (or some other non-numeric label). In V7, that worked because "Value" is not a valid number as was defaulting to 0 which matched the target label of 0 from the script. V8 is stricter than V7 and treats 0 and "Value" as different labels. V8 has now been updated so that when searching for a rectangle defined like this: "0,0,0,5000" (left,top,right,bottom) on a single column table with a column label of "Value" and row labels of RPM from 0..5000, the rectangle is now re-defined by V8 to be "@1,0,@1,5000". I.e. column 1 (the first and only column) and rows 0rpm to

5000rpm - the same as what V7 would have used.

Beta 51

- Updated EFILive_CmdLine.exe to support unique ID prefixes for identifying cax8 calibrations.
- Updated EFILive_CmdLine.exe to support AutoCal and FlashScan V3 devices.
- When working with multiple *.cax8 files, the Ctrl+Alt+O hot key was only reloading the most recently opened *.cax8 file instead of loading all *.cax8 files for the current tune file.
- The provider's unique ID value is now validated to ensure it is a valid identifier. To be valid it must begin with a letter or underscore and be followed by up to 29 additional letters, digits or underscores. I.e. Blue, _Fast, Red04 are all examples of valid identifiers. 4Square and Red Hot are invalid, 4Square does not begin with a letter or underscore, Red Hot contains a space character.
- Provider details are now updated correctly when multiple different providers are sharing the same parameter list.

Beta 50

- Fixed pass-thru and BBx reading and flashing error \$0503 "Script file not valid".

Beta 49

- Fixed calibration layout dimensions not being saved/restored correctly across application restart.
- Fixed cax8 descriptions not showing up if the EFILive supplied calibration description file is missing.
- Fixed some calibration descriptions not updating correctly when the user changes the display units. I.e. The description "Pulses per kilometer" was not changing to "Pulses per mile" when the user changed display units from pluses/km to pulses/mile.
- Fixed [F8: Tools]->[F8: Error Code] lookup not displaying complete information for error codes in the range \$0300..\$037F.
- Fixed some CMB reflash attempts that were failing with \$0301 (incorrect checksum).
- Floating point PIDs' values are now displayed correctly in the Scan Tool.
- Row-deposit composite-tables' address calculation is now handled correctly for all rows, not just the first row.
- Windows 10 automatically adds a read-only folder to the root folder of an SD Card when the SD Card is connected to a Windows 10 PC/laptop. When that SD Card is re-inserted into FlashScan V2, EFILive_Explorer hangs when attempting to display that read-only folder.

Beta 48-7

- Fixed pass-thru data logging not starting for some VPW based controllers.
- Send clear DTC commands to all controllers on the CAN bus, not just emissions

related controllers at end of read/flash process.

Beta 48-6

- Fixed EDA data logging that showed an incorrect value for main injection pulse time when both pilot1 and pilot2 pulse times were non-zero.
- OS numbers with more than 8 digits are no longer truncated to 8 digits when stored as meta data in data log files.
- When using BBR to read E83A or E83B controllers, the steam name "E83A" or "E83B" is now correctly stored in the *.ctz file's meta data.
- Using F10 and F11 to make the charts or gauges full-screen, no longer drags the main V8 window to the foreground.
- Curve fitting popup editor window no longer drags main V8 window to the foreground.
- Fixed E54(LB7) and E60(LLY) DSP5 tune selection PID. It now correctly displays the selected DSP5 tune instead of the DSP switch voltage.
- Serial wide band PID data is now logged from V3 devices correctly during pass-thru logging.
- *.cax -> *.cax8 conversions now correctly handle bit fields.
- Right-click "More Info" option for PIDs showed "Unspecified error" on second and subsequent invocations.

Beta 48 (3)

- Updated OBD error codes and messages in the \$0300..\$03FF range.

Beta 48

- Fixed CMC checksum issue.
- E54 (LB7) and E60 (LLY) serial numbers are now shown in the [F4: OBD] window.
- CMF VIN change is now supported in [F4: OBD]->[VIN Change].
- Disabled hotkeys for editing tune files when no tune file is open and/or when no *.cam file is present for the open tune file.
- Additional USB message management to mitigate the \$0101 error that may occur on some USB configurations.
- Tune files from A40 controllers that identify as "A46" can now be opened the V8 software.
- Selecting the "Next Scan/Tune Window" (hotkey Alt+F2 and Alt+F3) would cause the next window to be restored to its un-maximized size if it had been previously maximized.

Calibration Updates:

Dodge Cummins

- None.

Cummins Heavy Duty

- New operating system support for CM2350A
- New operating system support for CM2250 and CM2350A
- New support and updates for CM2450A and CM2670.
- Added V8 editing support for CM2150, CM2220, CM2250 and CM3250A.

GM Gas

- Added V8 editing support for E40
- Added V8 editing support for LS1A and LS1B.
- Added V8 editing support for E37, E38 and E67.

GM Diesel

- Added V8 editing support for E20, E86A, and E86B.
- Added V8 editing support for E54 (LB7) and E60 (LLY).
- Added V8 editing support for E35A and E35B.

Known Issues:

- When logging DMA PIDs (i.e. PIDs whose names end with "_M" or "_DMA"), if the ignition is switched off for an extended period while data logging but data logging is not terminated, then when the ignition is switched on again the data log automatically continues. However, the DMA PIDs may no longer return valid data.
- Workaround: EFILive recommends stopping the data log and restarting the data log when switching off the ignition for extended periods.

EFILive V7.5

Calibration Updates:

Dodge Cummins

- New support and updates to existing operating systems for the following controllers: CMC, CME and CMF.

Cummins Heavy Duty

- New operating systems for the following controllers: CM2250 and CM2350A
- New support and updates to existing operating systems for the following controllers: CM2350A.

GM Gas

- New support and updates to existing operating systems for the following controllers: E39, E78, E80, E82, E84 and E92.

GM Diesel

- New support and updates to existing operating systems for the following controllers:

E98.

Transmission:

- New support for the following controllers: T43, T76.

Enhancements:

- None.

Bug Fixes:

- None.

Known Issues:

- None.

FlashScan/AutoCal V3

Enhancements:

RC3 (V3.00.056)

- Recompiled code base with updated ARM tool chain.

RC3 (V3.00.055)

- None.

RC2 (V3.00.054)

- Custom menu options for selecting PIDs can now be optionally configured to automatically select a pre-defined PID list and/or automatically begin data logging or monitoring.

RC1 (V3.00.053)

- BCM flashing is now free and no longer requires a VIN license, the same as transmission controllers.

Beta 51 (V3.00.051)

- Added option Tune Tool -> F1: Tuning -> F4: Test OBD Network to test CAN J1979 and/or VPW (1x and 4x) vehicle networks for the presence of rogue modules that do not respect bus silence. Rogue modules can interfere with the read/flash process.
- Added power-up option to force the V3 device into thumb drive mode. To force the V3 device into thumb drive mode hold down the [Up] key while powering up the device - release the key once the splash screen is visible.
- Added power-up option to load EFILive's standard menu even when a custom menu is installed. To load the standard menu, hold down the [X] key while powering up the device - release the key once the splash screen is visible.

Beta 50 (V3.00.049)

·Updated controller identification algorithms.

Beta 49 (V3.00.047)

- Fixed Scan Tool -> F3: Scan Options -> F3: Onboard Modules which was reporting the "boot mode" and "run mode" status of Cummins light duty controllers the wrong way around.
- Full control of user defined menus, icons, images and themes is now supported via the user defined menu configuration. See the file \Documents\EFILive\V8\User Defined Menus\SampleCustomMenu.txt for additional information.

Beta 48-7 (V3.00.046)

- Fixed DMA PIDs logging as "N/A" for some controllers when black box logging.
- Options -> F2: Trouble Codes -> F1: Display DTCs now displays permanent DTCs alongside the usual current and pending DTCs.
- Added option to record OBDII data from VPW or CAN bus to *.xalm file for analysis by EFILive support.

Bug Fixes:

RC3 (V3.00.055)

- Fixed black box data logging stalling at startup when large number of PIDs (>50 channels) are selected.
- Fixed user defined splash screen image not displaying at power-up.
- Fixed firmware updates failing on a very small percentage of PCs (requires a boot block update to V3.00.005).
- Fixed file corruption that may be caused by USB message retries when transferring data to/from V3 using EFILive Explorer.
- Fixed data logging stall caused by a div-by-zero fault when EXT.WO2EQRx is selected and EXT.WO2LAMx is zero, i.e. when no wideband controller is connected.

RC2 (V3.00.054)

- If the SD Card contained no files or folders (or only hidden files/folders), then the Options -> F2: File System -> F1: Explore -> F1: Browse option would hang -requiring a power cycle to recover.
- Import/Export VIN licenses option was not validating correctly against the controller type, which may result in multiple VIN slots being allocated to the same controller.

RC1 (V3.00.053)

- User defined PIDs were not being loaded correctly from the user defined PIDs file when starting black box logging.
- Fixed external wide band data not being logged correctly during pass-thru logging

and not at all during black box logging.

- Fixed DSP tune switching for VPW based controllers: E54 (LB7) and E60 (LLY).

Beta 51 (V3.00.051)

- Fixed VIN license validation that was failing on some VIN licenses that had been transferred from V2 AutoCals to V3 AutoCals.

Beta 50 (V3.00.049)

- Fixed pass-thru and BBX reading and flashing error \$0503 "Script file not valid".
- When custom images are supplied with incorrect sizes the V3 device may crash when rendering those images. The firmware now validates the image size and will not attempt to draw images that have incorrect sizes.
 - Icons must be 48x48 pixels.
 - Splash and background images must be 240x320 pixels.

Beta 48-7 (V3.00.046)

- Calculated PID names are now preserved in log files when black box logging. Calculated PIDs are not displayed during black box logging but are now correctly displayed when the log file is re-opened in the V8 software.

V3.00.045

- Changed "Stream" to "Controller ID" in the "Record All Diags" output file.
- OS, Controller and Remote information was not displaying for scan and/or tune files on V3 devices when displayed in EFILive Explorer.
- When black box logging, the PID selection was incorrect when one or more inactive controllers existed prior to the controller/PIDs selected by the user.
- OS number was not displayed correctly for some CSP5 operating systems.
- Fixed "CSP4" spelling mistake in tune switch menu description.
- Serial wide band PID data is now transmitted correctly from V3 devices correctly during pass-thru logging.
- Reading and Flashing now allow extra time for other modules on the CAN/VPW bus to come back online before attempting to clear trouble codes.

V3.00.044

- Fixed "Clear DTC" option not working on VPW based controllers.
- When CVN Data or CVN History is not successfully retrieved from the controller a more user-friendly message is now displayed - instead of error \$0281 "No data retrieved".
- Word wrapping for different font sizes is now handled correctly so that some letters at the start and/or end of lines are not truncated.

V3.00.043

- To protect the integrity of files on the device, any attempt to read, modify or delete any file or folder using EFILive_Explorer.exe while a black box operation (read, flash or data logging) is in progress, will be rejected with the error \$010C "Device is busy".
- Update to ensure all TCM controllers do not require a VIN license to be flashed.

V3.00.042

- E45 (LB7) and E60 (LLY) serial numbers are now shown on the V3 screen when selecting: Diagnostics -> F1: Display Info -> F1: Display VIN/Info.

Known Issues:

- None.

FlashScan/AutoCal V2

Enhancements:

RC2 (V2.07.166)

- New operating system support.

RC2 (V2.07.165)

- New operating system support.

RC2 (V2.07.164)

- New operating system support.

Bug Fixes:

RC1 (V2.07.165)

- Fixed Access Violation when using File->Save As... after reading a controller.

Beta 48-7 (V2.07.164)

- Changed "Stream" to "Controller ID" in the "Record All Diags" output file.
- OS number was not displayed correctly for some CSP5 operating systems.
- LCD screen capture of some prompt messages are now allowed during pass-thru operation. Specifically, to allow screen capture of controller licensing messages for documentation purposes.

Beta 48 (3)

- Update to ensure all TCM controllers do not require a VIN license to be flashed.

Known Issues:

- None.

Documentation Updates

- EFILive Command Line Reference.pdf.

- [EFILive Error Codes.pdf](#).
- [EFILive V8 Reference.pdf](#).
- [AutoCal V3 User Guide.pdf](#).

Knowledgebase Updates

- None.